# **Keyboard shortcuts**

In addition to shortcut keys, standard MS Windows® Alt key shortcuts apply in some cases. Use the Alt key with the letter underlined in the menu. To cancel an operation, press **Esc** twice.

#### **General functions**

То	Press
start new design	(Ctrl)+(N)
open design	Ctrl)+(O) Or (Alt)+(F)+(O)
close design	[Alt]+[F]+[C]
save design	[Ctrl]+[S]
export machine file	[Shift]+[E]
save as	(Alt)+(F)+(A)
print design	Ctrl + P or
	Alt + F + P
show/hide Grid	Shift]+(G)
show/hide Overview window	Shift)+V
show/hide Color-Object List	Shift)+(L)
show Stitch List	Shift]+J
open Lettering dialog	(A)
measure distance on-screen	<u>M</u>
show measure tooltip	Ctrl]+[I]
undo command	Ctrl]+[Z]
redo command	Ctrl]+(Y)
cancel command	(Esc)
open online help	[F1]
exit application	Alt + F4
Digitizing functions	
То	Press or
activate Complex Turning	F2
activate Complex Fill	F3
activate Column A	[F4] [Shift]+[A]
activate Column B	F5
activate Column C	[F6]
activate Backtrack	Shift]+(X)
activate Appliqué	[F7]
activate Single Run	F8 Shift + N
activate Triple Run	<b>F9</b>
activate Motif Run	[F10]
activate Backstitch	[F11]
activate Stemstitch	F12
apply Satin stitch	[Shift]+[I]

#### Digitizing functions (cont)

То	Press	or
apply Tatami stitch	Shift]+(M)	
finish digitizing object (keep last stitch)	Enter 🚽	
finish digitizing object (omit last stitch)	Spacebar)	
finish digitizing free shape boundary	Enter 🚽	
delete last input point	<b>←</b> Bksp	
generate stitches	G	
switch between fill and run stitch	(Spacebar)	
switch between fill and manual stitch	Enter 🚽	
toggle Auto Underlay on/off	(U)	
activate Auto Trace To Vectors for selected artwork	Ctrl)+M	
activate Branching	I	
make combined vector object	Shift + H	

#### Selecting objects

То	Press
select all objects	Ctrl)+(A)
deselect all objects	[Esc] Or [X]
select by color	Ctrl]+[Alt]+[A]
activate Select Object tool	0
deactivate Select Object tool	Esc
select object at current needle position	Shift]+O
select multiple objects	Ctrl]+
select range of objects	Shift]+
select next object	[Tab≒]
select previous object	Shift]+[Tab≒]
select object beneath	2+
add next object to selection	Ctrl)+Tab≒
add previous object to selection	Ctrl)+Shift)+ Tab≝⊒
activate Polygon Select tool	Ctrl)+L
toggle stitch selection in Stitch Edit mode	Q
group selected objects	Ctrl)+G
ungroup selected objects	Ctrl)+U
lock selected object	(K)
* Stitch Edit tool selected	

#### Selecting objects (cont)

То	Press
unlock all locked objects	Shift]+(K)
select/deselect stitches	* (Tab与
* Stitch Edit tool selected	

#### Viewing designs

То	Press
toggle TrueView™ on/off	[T]
show/hide stitches	S
show/hide outlines	L
show/hide needle points	<b>†</b>
show/hide connectors	Shift + C
show/hide function symbols	Shift + F
view by color	Alt +C
hide others	[Shift]+[S]
show bitmaps	D
show vectors	[Shift]+[D]
zoom (marquee)	В
zoom to 1:1 scale (100%)	1
specify zoom factor	F
zoom in 2X	Z
zoom out 2X	Shift]+[Z]
zoom to all design	* [0]
zoom to selected objects	* [Shift]+[0]
zoom to product	* [Ctrl]+[0]
zoom to hoop	* [Alt]+[0]
zoom box in Overview window	Shift]+(B)
activate panning	Р
deactivate (temporarily) Auto Scroll	^ (Shift)
toggle Auto Scroll on/off	Ctrl]+Shift]+A
center current stitch in Design Window	[C]
return to previous view	V
redraw (refresh) screen	R
activate Stitch Player	Shift]+(R)
† Period * Zero ^ Hold down	
Viewing stitching sequence	
To travel	Press
to start of design	Home
to end of design	(End)
^ No object selected + Numeric keynag	honly no object

^ No object selected † Numeric keypad only, no object selected

### Viewing stitching sequence

To travel	Press
to next color	PgDn
to previous color	PgUp
to next object	Ctrl]+(T)
to previous object	Shift]+(T)
to next segment	^ [Ctrl]+(→)
to previous segment	^ [Ctrl]+←
to next function	^ Ctrl]+[PgDn]
to previous function	^ [Ctrl]+[PgUp]
to next trim	^ Ctrl +→
to previous trim	^ Ctrl]+←
1 stitch forward	^ →
1 stitch backward	^←
10 stitches forward	<b>√</b> ↓
10 stitches backward	^ <u>(†</u> )
100 stitches forward	<b>†</b> (+)
100 stitches backward	†
1000 stitches forward	†Shift++
1000 stitches backward	<b>†</b> [Shift] +[-]
^ No object selected † Numeric keypad only, no object	

\* No object selected † Numeric keypad only, no object selected

## Cutting & pasting objects

То	Press	or
cut object	Ctrl]+[X]	Shift]+Delete
copy object	Ctrl]+C	[Ctrl]+[Ins]
paste object	Ctrl]+[V]	Shift]+[Ins]
duplicate object	Ctrl]+D	
duplicate with offset	Ctrl]+Shift]-	+[D]
paste special > object	Shift]+[Ins]	
property position		
paste special > shift pasted	Ctrl]+Shift]-	+[V]
objects		
paste special > center at current stitich	(Ctrl)+(Alt)-	+[V]
paste special > start at current stitch	Shift]+[Alt]-	+[V]
delete selected objects or last object	Delete	

EmbroideryStudio e4 Reference Manual 1181

# Modifying objects & stitches

To move selected object	Press or click * [Ctrl]+⊕Ü
	* [Ctrl]+÷;;"
horizontally or vertically	
mirror horizontally	Ctrl]+1
mirror vertically	Alt + 1
nudge selected object	
	† [Shift] + <del>{}</del>
resizing	
activate Reshape Object tool	(H)
activate Show Stitch Angles tool	(Alt)+(A)
activate Show Reshape Nodes	Alt + N
tool	
	^ 鬥+Space
activate Stitch Angles tool	Ctrl]+(H)
activate Stitch Edit tool	E
add stitch angles (Complex	Ctrl)+(H)
Turning)	
remove overlaps	Ctrl]+Shift]+E
check design integrity	[]
* Drag object † Drag handle ^ Select co	ontrol point
Schiffli functions	
То	Press
insert Blatt/Stepp function	
insert Fadenleiter Plus/Minus	< >
insert Boring Tension Start/End	
insert RPM Plus/Minus	: "
change Schiffli borer depth	;
show Schiffli repeats	W